



**Pratt & Whitney Canada**

A United Technologies Company

**POPA**  
**June 12-14, 2014**  
**Savannah, GA**

**ENGINES**

**SUPPORT**

**INNOVATION**

**PEOPLE**

# EXPORT CLASSIFICATION

---

Check this box if presentation contains “*no technical data*” ☐ OR summarize the export classifications of all slides in this presentation as instructed below:

Instructions: Box 1 and one (1 ) of boxes 2-5 must always be completed	
	<b>Classification:</b>
1. Canadian ECL(s):	<b>N/A</b>
2. ECCN(s) (EAR):	
3. P-ECCN(s) :	<b>9E991</b>
4. USML (ITAR):	
5. P-USML:	

## PROPRIETARY NOTICE


This document is the property of Pratt & Whitney Canada Corp. (“P&WC”). You may not possess, use, copy or disclose this document or any information in it, for any purpose, including without limitation to design, manufacture, or repair parts, or obtain TCCA, FAA, or other government approval to do so, without P&WC's express written permission. Neither receipt nor possession of this document alone, from any source, constitutes such permission. Possession, use, copying or disclosure by anyone without P&WC's express written permission is not authorized and may result in criminal or civil liability.

# Disclaimer

The information contained herein has been set out in summary form and is provided for general reference purposes only and may be changed without prior notice. It should not be construed as creating any obligation on the part of Pratt & Whitney Canada Corp. While every care has been taken to avoid errors, Pratt & Whitney Canada Corp. makes no representations about the accuracy of these guidelines and accepts no responsibility for any error herein. In no event shall P&WC be liable for any damages whatsoever resulting from the misuse, misinterpretation, analysis, interpretation or application of any of the guidelines contained herein. The information contained herein does not replace or supersede the information contained in the appropriate airframe or engine maintenance manuals or other official publications. Always refer to the Pilot's Operating Handbooks (POH), Aircraft Flight Manuals (AFM), Engine Maintenance Manuals (EMM), Service Bulletins (SB) or other Service Information documentation for a complete text of the approved / recommended procedures and latest information.



# AGENDA



GA Inc.

Fleet Status

Engine Performance & Power Management

Engine Maintenance Philosophy

Best Practices







**Denis Parisien**  
Vice President  
General Aviation

**Carole Huculiak**  
Executive Assistant

# GENERAL AVIATION ORGANIZATION



## BUSINESS UNIT LEADS





# Fleet Status



**Pratt & Whitney Canada**

A United Technologies Company

Export Classification: No Technical Data

ENGINES


SUPPORT

INNOVATION

PEOPLE



# PT6A ENGINE STATISTICS



Total Produced

**43,000 +**



Flying Population

**23,000 +**



Certified PT6A Models

**70**



Total hours flown

**355.4** Million hours




High Time Engine

**52,502 (PT6A-65B)**

# PT6A ENGINE RELIABILITY

## TERMINOLOGY



### Key Rates

IFSD	In Flight Shut Down
BIF	Basic In Flight Shut Down
TIF	Total In Flight Shut Down
UR	Unplanned removal
BUR	Basic Unplanned Removal
TUR	Total Unplanned Removal

“Basic” – Event can be directly linked to the engine design or manufacture

“Non-Basic” – Event cannot be linked to the engine design or manufacture (e.g. weather, pilot induced, etc.)

Standard is 12 month rolling average



# PT6A-67B SERVICE EXPERIENCE





Engine flying hours	3.67 Million
Engines in service	758
High time engine	>20,969
Basic IFSD*	0.000
BUR*	0.018

\* Events / 1000 hrs (12 month rolling average)



PC-12 Legacy



Note: Rates calculated with 12 Months Rolling Average & 3 Months Lag period

# PT6A-67P SERVICE EXPERIENCE





<b>Engine flying hours</b>	0.52 Million
<b>Engines in service</b>	421
<b>High time engine</b>	>5,392
<b>Basic IFSD*</b>	0.000
<b>BUR*</b>	0.036

\* Events / 1000 hrs (12 month rolling average)





PC-12 NG



Note: Rates calculated with 12 Months Rolling Average & 3 Months Lag period

# PT6A ENGINE RELIABILITY

## Top Non-Basic Drivers



**Maintenance And Operation Are Key**



**Pratt & Whitney Canada**

A United Technologies Company

# Torque Limiter Oil Leak Field Inspection Update


ENGINES

SUPPORT

INNOVATION

PEOPLE

# Torque Limiter Oil Leak



## Issue

Oil leak on windshield during decent – 24 Jan 2013,  
Engine RY0086 – TSN 544

## Findings

Screws found loose with lockwire still intact, due to loss of screw pre-load. Indications that screws were not adequately torqued at manufacture.

Rubbing and fatigue crack evident in bellows due to resulting wear mechanism, loss of bellows retention.


## Action

Quality escape process with Honeywell completed  
CMM revised to specify torque value and require  
recording screw torque values

One time inspection SB14473



# Torque Limiter Oil Leak



Try to rotate spring pivot head in a clockwise and counterclockwise direction, and report any signs of movement.



Pivot spring assembly

In-situ inspection of torque limiters that are less than 1,000 hrs of service

Two findings to date  
Units being sent to P&WC for investigation with full support from supplier





**Pratt & Whitney Canada**

A United Technologies Company

# Engine Performance



ENGINES

SUPPORT

INNOVATION

PEOPLE

# PT6A Engine Overview



Export Classification: (Canadian ECL: N/A, US P-ECCN : 9E991)



P&WC Proprietary Information



**Pratt & Whitney Canada**  
A United Technologies Company

# PT6A Overview

## Two Spool, Free Turbine Design




Export Classification: (Canadian ECL: N/A, US P-ECCN : 9E991)

P&WC Proprietary Information



**Pratt & Whitney Canada**  
A United Technologies Company

# Engine Performance Check




Permits verification of engine condition over a wide range of ambient temperatures without exceeding torque or ITT limits


When should it be done?

- After engine installation
- Before and after hot section inspection
- After FCU change
- Engine troubleshooting

SIL PT6A-188



# Engine Performance Check



## How to measure/monitor performance

### ECTM

Engine performance check procedure per EMM and AMM

Check is performed at a given power where  $T_q$  and  $NP$  are constant

Target  $T_q$ ,  $ITT$ ,  $Ng$ ,  $W_f$  obtained from AMM for a given pressure Alt and temp

Engine run to set target torque and  $NP$  and actual  $ITT$ ,  $Ng$ ,  $W_f$  are compared to chart parameters


If values exceed chart parameters, then further troubleshooting is required

Not a true measure of margin


Data scatter due to ground run vs in flight



# Engine Margin




**Margin = Max Operating Limit – parameter @ rated power for the day**





# Effect on Performance




Typically picked up by trend monitoring


Compressor deterioration -	NG ↑ ITT ↑ Wf ↑
Restricted air inlet -	NG ↑ ITT ↑ Wf ↑
BOV open, or leaking valve seat -	NG ↑ ITT ↑ Wf ↑
P3 leak -	NG same, ITT ↑ & Wf ↑
Hot section deterioration –	NG ↓, ITT ↑ Wf ↑
Burnt CT vane	
High CT tip clearance	
Eroded CT blades	

A single engine parameter change usually means an indication issue

# Trend Monitoring



ECTM PWC S/N: MODEL:PT6A A/C: POS:1 297 RECS p. 1  
\*\* SMOOTHED- G (101705-021707) \*\* ALT:27000+/-1000ft PLOT DATE : 052707





**Pratt & Whitney Canada**

A United Technologies Company

# PT6A Engine Power Management


ENGINES

SUPPORT



INNOVATION

PEOPLE

# WHY TORQUE NOT TEMP?




Do you set your power to torque per POH?



# PT6A Engine Power Management


## Rating Philosophy



Engine provides rated power throughout its TBO .....provided:


- Operation is in accordance with the POH
- Engine is maintained in accordance with the EMM

**Torque is the primary power setting parameter**



# PT6A Engine Power Management

## Engine Deterioration




Setting power above POH Torque recommendations accelerates the normal deterioration of the engine → premature HSI / Overhaul

Can also lead to CT Blade creep  
high ITT + high Ng + time  
Change in microstructure, blade stretch leading to cracks








# Flat Rating



Permits max possible take-off power required over a wide range of ambient conditions



# Aircraft Mission





**Pratt & Whitney Canada**

A United Technologies Company

# Engine Maintenance Philosophy


ENGINES

SUPPORT

INNOVATION

PEOPLE

# Maintenance Philosophy



## Preventive Maintenance – Monitoring


Fuel Nozzle Replacement

Borescope Inspections

Engine Condition Trend Monitoring - ECTM



# Engine Maintenance



## Fuel Nozzle Inspection / Cleaning

- Inspection is recommended at 400 hour intervals
  - Extension based on inspection results

## Consequences of Poor Fuel Nozzle Maintenance

- **Cost You Money**
  - Local overheating/burning
  - Improper flame propagation
  - Combustion liner distress
  - Small exit duct burning
  - CT Vane burning
  - CT Blade distress


**Can also affect your warranty claims**

## Hot Section Borescope Inspection

- Aligned with Fuel Nozzle Cleaning



# Engine Maintenance - Preservation



## Inactive

**Engine is not operated on ground or in flight for a minimum of 10 minutes once oil temperature is stabilized.**

## Inactive for 0 to 7 days

Compressor and turbine desalination wash (salt laden environments)

Install Inlet and Exhaust Covers

## Inactive for 8 to 28 days

Do 0 to 7 day procedure

Desiccant bags and humidity indicators in exhaust

Seal all engine openings

Check relative humidity every 2 weeks, should be  $\leq 40\%$


Ref. EMM Chap. 72-00-00 for procedures above 28 days





# Compressor and Turbine Wash



**Effective way to prevent inlet case, compressor and turbine corrosion – SIL PT6A-206**



## SIL-125 Inadvertent Cutoff & Relights and POH

- **SIL PT6A-125 Operational awareness**
  - Blade microstructure damage due to overtemp caused by accidental cut-off & relight
  - Acceleration of Blade creep due to use of more power than allowed by POH
  - Issued January 2004
- **Revised Maintenance Manual April, 2004**
  - Address accidental cut-off & relight overtemp
  - Lessons learned applied across all PT6A Maintenance Manuals

# SIL PT6A-125 CT Blade Fractures



Accelerated Blade Creep

It is essential to use the correct power setting procedures to assure the integrity of the engine.

Engines operated regularly beyond the recommended power settings of the POH, but still below the defined temperature redline settings and EMM over-temperature chart limits, may experience accelerated CT Blade Creep.





# Operational Best Practices




**Pratt & Whitney Canada**

A United Technologies Company



# It is All About Temperature ...



## STARTING :


General Rule : The Cooler, The Better !!!

## ASSISTED START :

- Experience has shown that Ground Power Unit (GPU) assisted starts are cooler.



# It is All About Temperature ...



## STARTING :

General Rule : The Cooler, The Better !!!


BLEED OFF DURING START:

- Selecting bleed off at engine start decreases the maximum starting temperature.
- Reducing peak temperatures will have a direct impact on blade life.





# It is All About Temperature ...



TAXIING :

Use of Reverse Power :

- Use of reverse power to push back the aircraft from the ramp increases engine operation temperature.
- Park aircraft away from the ramp if push-back carts are not available.



# It is All About Temperature ...




CLIMBING / CRUISE :

Climb Setting :

- Select CLIMB setting on Power Lever at earliest opportunity based on obstacle clearance.
- This will reduce engine operation time at high temperatures. **Refer to AFM / POH**



# It is All About Temperature ...



CLIMBING / CRUISE :


Reduced Power Operation :

- Where operations permit, most benefit is achieved by reducing power and ITT during climb and cruise.
- By reducing power (derated operation), the cumulative deterioration done to a component during the interval between refurbishments may be reduced.

**Refer to AFM / POH**



# It is All About Temperature ...




LANDING / SHUTTING DOWN :

Use of Reverse Power :

- Use of full reverse power increases engine operation temperature
- PCL to Beta (flat pitch) sufficient
- Limiting the use of reverse to necessary cases only, will contribute to increased hot section life.



# It is All About Temperature ...




## LANDING

Propeller Flat Pitch at Landing :

- When landing, especially on an unpaved runways it is recommended to use flat pitch (disking) and not full reverse.
- This will reduce the possibility of foreign object ingestion and consequential FOD damage to compressor.
- In addition, diskling will not increase engine operation temperature to the extent of full reverse.



# It is All About Temperature ...



## LANDING / SHUTTING DOWN :



### Cool Down Before Shutdown :

- An engine cool down period of two minutes at GI (ground idle) prior to shutdown will assist hot section temperature equalization.
- Reduces residual heat build-up in the engine/nacelle
- Reduces the level of fuel nozzle coking.





# FOD & Ice Protection



© Pratt & Whitney Canada Corp. All rights reserved



# FOD PREVENTION

## General

Use inertial separator during taxi operation and icing conditions

Check that the tarmac is clean during walk-around





Avoid dropping safety wire or rivets in the air inlet plenum area

Install inlet / exhaust covers when aircraft not in use


Do not use reverse thrust at low ground speed

What damages the prop may damage the compressor

## Damage example 1<sup>st</sup> stage Compressor



# FOD PREVENTION



**First Stage rotor icing damage**

## **First Stage rotor icing damage**

- First stage blade bending is consistent with an impact from a soft body that could be related to formation of ice

## **Preventive Field Actions**

- Troubleshooting chart improvement made to add unusual compressor high pitch noise to trigger maintenance action
- Add a periodic inspection for visual borescope inspection on First Stage Rotor


**Q: When should the inertial separator be activated?**

**A: Check the POH.**



# FOD PREVENTION

## Inertial Separator Operation



### Ground

Avoid starts with separator open


Watch ITT closely during deployment

### Flight

Reduce power by 10% before deployment

Allow for deployment time before entering icing conditions


Watch ITT closely during deployment



**Pratt & Whitney Canada**  
A United Technologies Company

# ITT EXCEEDANCES

## Main Causes



Adding Fuel too early - 13% Ng Min

Inertial Separator deployment in flight with no reduction in power

Taxiing in Ground Idle with bleed ON / inertial separator ON

Compressor loading drives Ng down, ITT up

Lower Ng means less cooling air for hot section components


Low Battery Power



**Pratt & Whitney Canada**  
A United Technologies Company



# ITT EXCEEDANCES



Always refer to the EMM for the required actions

## Area A:

Determine and correct cause of O/T


For start O/T, perform visual inspection through exhaust duct

Record in log book

## Area B: Perform Hot Section Inspection

## Area C:

Ship Engine to approved overhaul facility for light overhaul inspection due to overtemperature



Temperature Limits



**Pratt & Whitney Canada**  
A United Technologies Company



# PROPELLER STRIKE



Potential secondary damage




Power Turbine tip  
rubbing



Labyrinth air seal  
rubbing



# PT6A ENGINE MAINTENANCE




## “Know Your PT6A Turboprop”

Booklet released with “need to know” information


- Now Available at [www.pwc.ca](http://www.pwc.ca)
- Engines → Turboprops → PT6A
- Related Info (bottom right)




# Summary




## High Temperature Pressure Inside Engine




## Engine has Limits




## Engine Stress Costs Money



## Follow EMM / POH



## Monitor Engine Parameters



## Save Money !



# PRATT & WHITNEY



# DEPENDABLE

[WWW.PWC.CA](http://WWW.PWC.CA)



**Pratt & Whitney Canada**

A United Technologies Company